




Screw Compressor Control and Data Logging. Model A-32-S



FEATURES: -

Automatic or Manual Control
Oil Pressure Start before Motor Start
Motor Start Fully Unloaded
0 to 100 % Load Unload.
High and Low Pressure Alarms
High and Low Temperature Alarms
Alarm Delays
Pump Down Set Point for Turn OFF
Load and Unload Delays
Fast Load Set Point
Fast load delay
Manual for Running Compressor
Manual Load and Unload Switches

OTHER FEATURES: -

Oil Heater.....Oil Cooler (water/liq. Injection)......Economizer Output Volume Ratio Control and Position Input......Data Logging......Alarms Logged Warnings Logged......20 Character by 4 Line LCD.......7 Digit LED Displays Compressor Load and Run Indicators......Easy Menu Driven Setting of Functions Remote Run Input......Fully Microprocessor Controlled.......Connect to TempScan Instant Indication of Pressures/Temperatures......Variable Speed Drive.......

Distributor :-		